



subject: **Changes to *diag frm on-line internal_port***

date: **October 21, 1996**

from: **BNS-2000 Customer Support
1800WE2CARE**

PRODUCT DOCUMENTATION NOTICE

This memo describes changes made to the **diag frm on-line internal_port** command in BNS-2000 for a V.35 configured port.

An information message and a continue prompt have been added as follows:

If TEST TYPE is internal_port:

INFO:

Before continuing with this test, remove all external equipment from the port being tested.

CONTINUE TESTING [yes, no: +(yes)]:

This new information message and prompt appear after:

For DIAGNOSTIC TYPE on-line and SERVICE TYPE v35:

PORT NUMBER [1-4]:

TEST TYPE [internal_port, local_modem, remote_modem:
+(internal_port)]:

This PDN modifies product document Data Networking Products Frame Relay Module Reference, CIC ID 255-100-205 (Issue 2), page 6-20.