



subject: **New Error Codes for "Connection not completed" Message**

date: **July 3, 1996**

from: **BNS-2000 VCS Customer Support
180WE2CARE**

PRODUCT DOCUMENTATION NOTICE

This memo describes 2 new error codes added to the "Connection not completed" message documented in the Data Networking Products Terminal User Guide.

Two new error codes, 59 and 60, can appear in message;

Connection not completed. Contact Network Administrator.
(`<error code>`, `<node address>`)

Error codes 59 and 60 indicate that, in the path between the terminal user and the requested destination: (a) a Trunk-PQ is configured for **CIR only**, or (b) the configuration of a Trunk-PQ does not match on both ends of the trunk.

Consult product document Data Networking Products Terminal User Guide, CIC ID 255-100-236, Issue 1, Appendix A, Table A-1 for more information.