



subject: **Changes to *dmeas trunk*** Documentation

date: **October 21, 1996**

from: **BNS-2000 Customer Support
1800WE2CARE**

PRODUCT DOCUMENTATION NOTICE

This memo describes a change to the documentation for the **dmeas trunk** command.

The description for the `MINUTES` field, should be modified to read as follows:

For all trunks except Trunk-64 and Trunk-DDS, the number of minutes in which measurements were being collected. If there were no trunk failures the number is equal to the number of minutes in the entire interval. If the number is less than the number of minutes in the entire interval a trunk failure is indicated.

This PDN corrects product document Data Networking Products Trunk Module Reference, CIC ID 255-100-213, page 6-32.