



subject: **Changes to Adding a Group Address** Procedure in BNS-2000  
SMDS Guide

date: **October 21, 1996**

from: **BNS-2000 Customer Support**  
**1800WE2CARE**

*PRODUCT DOCUMENTATION NOTICE*

This memo describes a change to the documentation that describes the procedure to add a group address in an ICI network.

Under Step 2, *Select the group address*, of Procedure *Adding a Group Address*, the following information should be appended to the existing paragraph:

If the group-addressed PDU is to travel to the GAA network through private interLATA trunks, then the 6 digits must also be assigned to a BNS-2000 node in the GAA network. This node must be connected to the remainder of the network for routing of group addresses that begin with the 6 digits to succeed through the private interLATA trunks.

This PDN corrects product document BNS-2000 SMDS Guide, Release 2.0 (Issue 1), CIC ID 255-184-104, page 3-21.